

HWBI AUTO INSPECTIONS
9 - PHOTO INSPECTION

Inspection Date: Dec 4, 2020
Time: 9:00 A.M.



NAME: Joe Smart
Address: 222 Nowhere way, Sacramento, CA 95825
Phone: 916-222-XXXX Email: Joe@gmail.com
Vin#: 626M09712
Year: 1962
Make: Oldsmobile
Model: Starfire
Style/Body: 2dr Coupe
Engine: 394 Cu. in. V8

HWBI Inspection
Inspector: Ernie Jaramillo
Sac, CA 95825
Phone: 916.416.6640
Email: ejj@hwbi.net
Website: hwbi.net



NOTE:

Hwbi vehicle inspection is a non-invasive, visual examination of accessible areas of the automobile, performed for a fee, which is designed to identify defects within the automobile and observed material by the inspector. The scope of the work may be modified by the client and Inspector prior to the inspection process.

Hwbi has been in the Auto Industry for 35+ years and follows the Standards of Practice pertaining to the automotive industry to support the inspection and manufacturing of safe and reliable products, which are produced and continually improved to meet or exceed customer and regulatory authority requirements. (Auto Check or Car Fax upon customers approval)

EXTERIOR

Xxxxxx xxxxxxx, SACRAMENTO, CA 95825

Exterior is in good shape, no dents, no major scratches. Chrome is in good could use a polish in places. All chrome strips, body moldings are in very good shape. Very minor scratching on the trunk, easy to buff out. Overall rating A



Hwbi follows the Standards of Practice pertaining to the automotive industry to support the inspection and manufacturing of safe and reliable products, which are produced and continually improved to meet or exceed customer and regulatory authority requirements.

INTERIOR / MOTOR

1. Interior Condition:

Inspect: Yes No Repair FYI

Interior is in excellent condition, AC Blows Cold, Power steering good (no noises). Upholstery is good shape, gauges all work. Transmission shifts good (no noises)



Inspect: Yes No Repair FYI

Engine runs good, hoses and connections are good. No leaks gas, oil or water. Fan belts are a bit worn could be replacing.



Hwbi follows the Standards of Practice pertaining to the automotive industry to support the inspection and manufacturing of safe and reliable products, which are produced and continually improved to meet or exceed customer and regulatory authority requirements.

Extra Pics / Trunk / Under body /Rust etc.

1. Trunk / Under body, Condition:

Inspect: Yes No Repair FYI

Trunk and Under body pics go here as requested by Client:

Minor scratches on Trunk could be buffed out



Inspect: Yes No Repair FYI

Extra Pics and inspections go here:



REPORT SUMMARY

Engine: Fan belts are a bit worn, could use replacing.

Exterior: Minor Scratches on Trunk could be buffed out.

Original Upholstery, Original wheel covers are available, All Chrome, New Skirts, all gauges work, Owners Manual, Halogen Headlights, April 2015 California Tags.

(Extra parts worth \$2500 - \$5,000 not included in sale but price is negotiable)

N.A.D.A Classic Car Guide Price: Average - \$23,625 High - \$45,750

Thank you again for choosing HWBI Home Inspections. If you have any questions or concerns Please contact me:

HWBI Auto Inspections,
Ernie Jaramillo

(916)416-6640

Email: ejj@hwbi.net

Website: www.hwbi.net

1999-2021 Copyright © hwbi.net all rights reserve worldwide
and all the websites in this group

